

INSPECTION WORKSHEET FOR LOADING REPORT

Report No. : FU-YE100113

TO : ITC AGENCY
ATTEN : YURIY
FROM : CCIC-FJ

APPLICANT : ITC AGENCY
SUPPLIER : FOSHAN WORLDPRICE IMPORT & EXPORT CO., LTD
MERCHANDISE DESCRIPTION : WILLOW BASKET
PO. NO. : -
LOADING DATE : FEB.08,2010
LOADING PLACE : LINYI CITY, SHANDONG, CHINA.

This is to report that on the date Feb. 08, 2010 at the request of the applicant, we attended the factory located in LINYI CITY for the purpose of condition of packing and quantity checking of following consignment.

1. QUANTITY CHECKING: (No. of cartons of the entire batch)

Result:

Total Quantity	Pieces/Sets	Cartons
Order Quantity	5,680PCS	253
Shipment Quantity	5,677PCS	253

Remark: The actual shipment quantity was 5,677pcs/253ctns instead of 5680pcs that required by client. The following moldy 3pcs were not loaded: P001S/4 XL(1PC) ,M(1PC) ,S(1PC).

2. PRODUCT DESCRIPTION, STYLE AND COLOUR:

Check against PO./Specification.

- The inspected samples were found similar to the description of PO./Specification.

Check against sample submitted by applicant.

- No reference sample was provided for style & colour comparison.

* * * * *

Report No. : FU-YE100113

3. PACKAGING CHECK: (Sample size level II 12 pkgs were checked for packaging)

- Result : Not conformed. Refer to special attention .
- Packaging method : Refer to the inspection photos.

special attention :

The actual packing form of Item **N093PC** was ctn rather than woven bag on **INSPECTION & SURVEY APPLICATION FORM**.

4. SHIPPING MARK:

Conformed.

5. LOADING SURVEY:

Details were found as below:

Quantity	5,677Pieces (253pkgs)
Weather Condition	cloudy
Container No.	CLHU8381707
Size Of Container	40'HQ
Seal No.	N943259 / CCIC-SD 010511
Tractor No.	鲁 B 95251
Loading Time	16: 25-18: 06
Our Inspector Arrival Time	09: 10
Our Inspector Leave Time	18: 10

Note: For details, please refer to digital photos.

* * * * *

Report No. : FU-YE100113

PHOTO ATTACHMENT



CONTAINER



EMPTY CONTAINER



TRACTOR



LOADING



LOADING



LOADING



FULL CONTAINER



CLOSE HALF DOOR



AFTER LOADING



CCIC'S SEAL



SHIPPING COMPANY'S SEAL

-END-